

## **Servicii reparatii auto DB 12 FPP**

I.D.: 102462814

---

Data publicarii 05.09.24 Coduri CPV 50110000-9 50112100-4

---

Pretul estimativ: 1.355,00 RON - 1.355,00 RON

---

Descriere: Inlocuit termoflot, curatat instalatie apa si desfundat calorifer caldura, sudat toba la auto marca Dacia Logan MAI 34279 ( DB 12 FPP)

---