

---

## Servicii de vulcanizare

I.D.: 53719921

---

Data publicarii	27.01.21	Coduri CPV	50116500-6
-----------------	----------	------------	------------

---

Pretul estimativ: 1.319,00 RON - 1.319,00 RON

---

Descriere: Servicii de echilibrare inclusiv adaos de plumb turism - janta otel 14"-15" - 8 x 78.00 lei/roata = 624.00 lei + TVA Servicii de montare anvelopa turism - janta otel 14"-15" - 18 x 7.00 lei/roata = 126.00 lei + TVA Servicii de montare roata turism - janta otel 14"-15" - 78 x 4.00 lei/roata = 312.00 lei + TVA Schimbat valva - 4 buc X 7.00 lei/buc = 28.00 lei + TVA Servicii de echilibrare inclusiv adaos de plumb turism - janta otel 16"-18" - 13 x 8.00 lei/roata = 104.00 lei + TVA Servicii de montare anvelopa turism - janta otel 16"-18" - 11 x 7.00 lei/roata = 77.00 lei + TVA Servicii de montare roata turism - janta otel 16"-18" - 12 x 4.00 lei/roata = 48.00 lei + TVA

---