
Reparat masina de spalat

I.D.: 65176687

Data publicarii 12.01.22

Coduri CPV

50800000-3

Pretul estimativ: 168,06 RON - 168,06 RON

Descriere: Reparat masina de spalat Indesit ;- remediat scurgere, schimbat burduf de scurgere detergenti
