
Reparatie RICOH MP201SPF

I.D.: 47672415

Data publicarii	30.06.20	Coduri CPV	50313200-4
-----------------	----------	------------	------------

Pretul estimativ: 1.341,98 RON - 1.341,98 RON

Descriere: Oferta neacceptata in termen: Reparatia include:Cod Piesa Denumire Piesa Cantitate (buc)
B0441286 FRONT DOOR 1 Manopera 1; Cod Piesa Denumire Piesa Cantitate (buc) D1273802
Transfer roller 1 AE011086 Hot roller 1 AE020164 Pressure roller 1 AE031044 Hot Roller
Bearings 2 AE044059 Hot Roller Stripper Pawls 3 AW100088 Thermistor 1 AE031035 Press
roller bushing 2
