
Servicii de reparare uscator de rufe cu condensare Heinner HCD-V804B

I.D.: 66817818

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 01.03.22 | Coduri CPV | 50532000-3 |
|-----------------|----------|------------|------------|

Pretul estimativ: 428,56 RON - 428,56 RON

Descriere: Servicii de reparare uscator de rufe cu condensare Heinner HCD-V804B, 8 kg, 15 Programe, Display LED, Baby Care, Clasa B, Alb Manopera :159.66 lei Piese: DOHOHCDV804SB (carlig | Door Hook, E.V. # 402 (412) HCD-V804SB) - 12.60 lei DOLAHCDV804SB (inchizator usa | Door Latch, E.V. # 627 HCD-V804SB) - 42.02 lei
