

Reparatie Ford Ecosport

I.D.: 58401100

Data publicarii	30.06.21	Coduri CPV	50110000-9 50112000-3
-----------------	----------	------------	-----------------------

Pretul estimativ: 870,41 RON - 870,41 RON

Descriere: Manopera:inlocuit discuri+placute frana fata,inspectie sistem franare fata+spate:192.01 lei;
Piese:discuri de frana,placute frana:678.40 lei. Total:870,41 lei
