

---

## Servicii de reparatie ploscar Meiko

I.D.: 93369086

---

Data publicarii	12.02.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ: 2.206,00 RON - 2.206,00 RON

---

Descriere: reparatie ploscar Meiko 1 buc. conector dozator complet pt bazin (9735748), pret 759 lei/buc. fara tva 1 buc. conector pompa peristaltica (9669552), pret 647 lei/buc. fara tva manopera reparatie, pret 800 lei fara tva

---