

---

## Serviciul de reparatie suflanta Makita

I.D.: 50702215

---

Data publicarii	16.10.20	Coduri CPV	50800000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 109,33 RON - 109,33 RON

---

Descriere: Serviciul de reparatie suflanta Makita BHX2501 consta in urmatoarele proceduri: - constatarea defectiunilor - identificarea pieselor defecte - inlocuirea pieselor defecte (filtru aer, filtru pasla, ulei.) - testare/predare

---