

---

## Servicii de intrretinere VW TRANSPORTER

I.D.: 83873707

---

Data publicarii	23.06.23	Coduri CPV	50112200-5
-----------------	----------	------------	------------

---

Pretul estimativ: 1.287,95 RON - 1.287,95 RON

---

Descriere: Servicii de reparare si intretinere VW TRANSPORTER ce includ: inlocuire ulei motor 504/50700,buson baie ulei,filtru ulei materom,filtru aer materom,filtru polen materom,filtru combustibil materom,lichid frana,aerisire instalatie combustibil,service lichid frana,verificat eficacitate franare.

---