

REPARATII CAMERE DEFECTE IN URMA TRASNETULUI

I.D.: 103713333

Data publicarii 30.09.24 Coduri CPV 50800000-3

Pretul estimativ: 15.586,01 RON - 15.586,01 RON

Descriere: -3 Diverse servicii de intretinere si de reparare (Rev.2) Descriere: CAMERA 5MP BULET IP KM-IP531 BUC 6 289,52 CAMERA 5MP BULET IP KM-IP231SW-K BUC 2 205,88 CAMERA 2MP BULET IP KM-IP239M BUC 7 210,08 CAMERA 2MP DOM IP KM-IP239C BUC 2 201,68 CABLU FTP CU SUFA EXTERIOR Schrack BUC 164 3,78 CABLU FTP EXTERIOR Schrack BUC 738 3,36 DOZE IP 65 BUC 17 10,20 PRESETUPE PG 9 BUC 32 1,10 TABLOU ABS BUC 1 152,30 SIGURANȚE 10A BUC 1 50,42 CABLU MYF 16 mm ML 7 10,92 PAPUCI 16mm BUC 2 2,4 CANALET 25X40 ML 8 3,36 SWICH POE KMW 8 +2 PORTURI POE BUC 1 348,74 MUFE RJ 45 PASSTROUTH BUC 42 2,50 PATCH 2M BUC 2 5,88 CABLU MYM 3X1,5 ML 26 6,72 FASETE PLASTIC BUC 523 0,75 SURGE PROTECTION BUC 4 138,65 ACCESORII BUC 1 352,00 HOLSURUB BUC 63 0,18 DIBLUCU HOLSURUB 8X 80 BUC 62 1,10 DIBLU CU HOLSURUB 10X 100 BUC 4 1,60 PDU 8 P BUC 1 120,44 DOZE 4M AVE BUC 1 12,61 PRIZE Schuko BUC 2 14,90 CANALET 100X60 ML 2 14,29 PD DESCARCATOR 20KA BUC 1 197,48 ÎWITCH 8P DLINK BUC 1 130,25 MANOPERA ORE 75