

---

## **INLOCUIRE SENZOR TEMPERATURA DUPA CATALIZATOR, REMIAT CABLAJ AC MB LKW ACTROS**

I.D.: 58710156

---

Data publicarii	08.07.21	Coduri CPV	50112200-5
-----------------	----------	------------	------------

---

Pretul estimativ:	1.857,47 RON - 1.857,47 RON
-------------------	-----------------------------

---

Descriere:	Diagnoza-purificare gaze arse defect, inlocuit sensor temperature,efectuat test, remediat cablaj AC
------------	---

---