
Inlocuire piese defecte la Cromatograf de lichide HPLC Alliance Water

I.D.: 15995570

Data publicarii	10.11.16	Coduri CPV	38432000-2
-----------------	----------	------------	------------

Termenul limita pentru depunere:	14.11.16	Pretul estimativ:	53.269,00 RON
----------------------------------	----------	-------------------	---------------

Descriere: Inlocuire piese defecte la Cromatograf de lichide HPLC Alliance Water (torpedo-ul primar defect- eroare solv delivery motor lost sync). Necesetia inlocuire: pompe- Assy pump w/seal wash, enhanced (cod prod:wat700001031)- cantitatea 2 buc. si degazor 2695 degasser tray (cod prod.wat700001219)-cantitatea 1 buc
