

Reparatie refulator 525 BX

I.D.: 64322207

Data publicarii 14.12.21 Coduri CPV 16800000-3 50800000-3

Pretul estimativ: 577,32 RON - 577,32 RON

Descriere: Reparatie refulator 525 BX, conform deviz: carter - 1 buc; rulment - 2 buc; semering - 2 buc; carburator - 1 buc; filtru aer - 1 buc; garnitura carter - 1 buc; manopera.
