
Reparatie Receptor Leica Zeno20

I.D.: 71266983

Data
publicarii 14.07.22

Coduri CPV

50433000-9

Pretul
estimativ: 2.520,00 RON - 2.520,00 RON

Descriere: Servicii reparatie (inlocuire placa de baza), upgrade software, reconfigurare receptor Leica Zeno20 ZRover serie de fabricatie: 3165525. Reconfigurare setari receptor in ZenoConnect Reconfigurare porturi comunicatie in ZenoConnect Reconfigurarea fisierului de initializare MSurvey.ini in FieldGenius
