
reparatii tamplarie

I.D.: 43633898

Data publicarii	26.07.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ: 630,25 RON - 630,25 RON

Descriere: INLOCUIT: broasca aluminiu - 1 buc., maner usa - 2 buc., butuc - 1 buc., contraplaca - 1 buc., balamale rapide - 4 buc., PANEL PVC MARON- 1 buc inlocuit si efectuat orificii, efectuare reglaj usa.
