
Servicii de reparatie ecograf CX50 prin inlocuire de piese

I.D.: 72494604

Data publicarii	23.08.22	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ:	49.342,96 RON - 49.342,96 RON
-------------------	-------------------------------

Descriere: Servicii de reparatie ecograf CX50 prin inlocuire de piese Piese de schimb folosite pentru reparatie: -453561473244 PCB Assy, Morpheus Power Board -453561769362 Svc, EBOX Assy, HW C.X, PWD, CX50, FRU
