

Interventie service BC 5150

I.D.: 49016111

Data publicarii	17.08.20	Coduri CPV	50421000-2
-----------------	----------	------------	------------

Pretul estimativ: 7.874,40 RON - 7.874,40 RON

Descriere: Interventia service include: 1. Pinaster Mainboard x 1 buc. x 0 lei (placa de baza) 2. 3107 Power Source PCBA x 1 buc. x 7041.60 lei (sursa de alimentare) 3. Manopera service x 3 ore x 161 lei/ora Transport service x 636 km x 0.55 lei/km
