
Servicii de reparare schimbator in placi

I.D.: 99927087

Data publicarii	12.07.24	Coduri CPV	50531200-8
-----------------	----------	------------	------------

Pretul estimativ: 11.379,00 RON - 11.379,00 RON

Descriere: ervicii de reparare schimbator de caldura in placi Alfa Laval model T6-BFG, 50 plates, ALLOY 316, prin inlocuire de placi, garnituri si accesorii uzate
