
Reparatie Furtun hidraulic si ulei hidraulic

I.D.: 86226777

Data publicarii	21.08.23	Coduri CPV	44165100-5 71631100-1
-----------------	----------	------------	-----------------------

Pretul estimativ: 621,35 RON - 621,35 RON

Descriere: Reparatie Furtun hidraulic pt Caterpillar tip 301.8, nr inscriere PT IF 421 Ulei hidraulic H 46 (Canistra 20 L) - 1buc / 400.88lei KILOMETRII EXTERIORI (in timpul programului de lucru) - 20km / 118.80lei FURTUN HIDRAULIC ASAMBLAT DN 6 L-600mm - 1buc / 101.67lei
