
Achizitionare servicii de reparare sistem climatizare camin Drâmbar

I.D.: 48920857

Data publicarii	13.08.20	Coduri CPV	50700000-2
-----------------	----------	------------	------------

Pretul estimativ: 100,00 RON - 100,00 RON

Descriere: Achizitionare servicii de reparare sistem climatizare camin Drâmbar: Constatate si resetare instalatie de incalzire/racire - 1 buc., Olandez alama 1 1/4" - 2 buc., Cot alama 1 1/4" I - E - 4 buc., Piesa FE PPR 40x1 1/4" verde - 2 buc., Cot PPR 40-90 verde - 6 buc., Mufa PPR 40 mm verde - 4 buc., Teava PPR Watertec 40 mm - 2 buc., Banda adeziva anticondens 50x3x15m - 1 buc., Lucrari si servicii de montaj - 1 buc., Demontare ventiloconvector, inlocuire motor ventiloconvector - 1 buc., Motor ventilator ax dublu - 1 buc., Filtru de aer - 2 buc., Telecomanda ventiloconvector - 1 buc.
