
REPARATIE GENERATOR DE SUDURA TRIFAZAT TW220DC

I.D.: 103343031

| | | | |
|-----------------|----------|------------|-----------------------|
| Data publicarii | 23.09.24 | Coduri CPV | 50800000-3 50000000-5 |
|-----------------|----------|------------|-----------------------|

| | |
|-------------------|-------------------------|
| Pretul estimativ: | 193,98 RON - 193,98 RON |
|-------------------|-------------------------|

Descriere: BUJIE BPR6ES (E- MAXI 0242235707, GARD - BPR6ES) * (12L2) 9807956846 BOBINA INDUCTIE * (7E) 30500Z5T003 ULEI SYNTETIC QUARTZ ENERGY 10W40, BIDON 1L * (21F) QUARTZ7000EGY10W40B1L CLESTE MASA 600A, 95mm TOLEDO * TW-804184 CLESTE PORT ELECTROD 400A/50MM VRAC (R12.4.6.2) (v=712019) * TW-804171 MANOPERA REPARATIE IN GARANTIE, NORMA DE TIMP (REPAIR COST) * UMG MANOPERA, NORMA DE TIMP * UM
