
Servicii de reparare si inlocuire VW Transporter A-10182 BORCEA

I.D.: 84098178

Data publicarii	26.06.23	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 850,00 RON - 850,00 RON

Descriere: VW Transporter, VIN: WV2ZZZ7HZ8H038445 Necesari de inlocuit : servicii de inlocuire "Supapa recirculare gaze, 038131501BF " buc 1 690.00 690.00 Manopera ora 1.45 110.00 160.00
