
Reparatie cu inlocuire piese de schimb la masinile de spalat industriale Imesa Lm23 si Lm40

I.D.: 84131242

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 28.06.23 | Coduri CPV | 50000000-5 |
|-----------------|----------|------------|------------|

Pretul estimativ: 11.514,08 RON - 11.514,08 RON

Descriere: Reparatie cu inlocuire piese de schimb la masinile de spalat industriale Imesa Lm23 si Lm40
Imesa Lm23 - ELECTROVALVA ALIMENTARE APA PRINCIPALA METALICA 230V - ELECTROVALVA ALIMENTARE APA CATRE CUTIR DETERGENTI CU O IESIRE 230V - ELECTROVALVA ALIMENTARE APA 3/4 230V (2buc) - ELECTROVALVA ALIMENTARE APA CU DOUA IESIRI Imesa LM40 - RULMENT 193TN222OL40 - RULMENT 193CUR2226P - INEL ETANSARE 3940AT131612 - SNUR ORING '5 - INEL ETANSARE 3940AT161915 (3 buc) - BUCSA ETANSARI STRUNG
