
Reparatie pompa submersibila Flygt 2,4kw

I.D.: 42769129

Data publicarii	15.05.19	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ: 2.976,00 RON - 2.976,00 RON

Descriere: Demontat pompa,efectuat constatare si schema de bobinaj,extras bobinajul vechi,spalat,curatat,confectionat izolatie si bobine,introdus bobinele in stator,efectuat conexiuni,consolidat bobinajul,impregnat,curatat de lac dupa impregnare,inlocuit rulmentii 6204 SKF,inlocuit kit etansare mecanic, montat,probat
