
Servicii de reparatie electrocauter VIO 300S

I.D.: 70744238

Data publicarii	27.06.22	Coduri CPV	50422000-9
-----------------	----------	------------	------------

Pretul estimativ: 11.225,00 RON - 11.225,00 RON

Descriere: Servicii de reparatie electrocauter VIO 300S conform raport service nr. 60 din 17.06.2022
Contine: Diagnosticare Modul PCB Power Supply 30140-810 Recalibrare aparat Efectuare update software la versiunea 2.0.4 Efectuare verificare si intretinere generala Intocmire buletin verificare cu valabilitate 12 luni Transport Manopera
