
Servicii de reparare CT-15-CRN

I.D.: 66817579

Data publicarii	28.02.22	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 8.355,17 RON - 8.355,17 RON

Descriere: Servicii de reparatii constand in inlocuit chiulasa + supape, distributie si consumabile.
Materiale inlocuite : 1. Set garnituri - 1 buc; 2. Set supape admisie - 1 buc; 3. Set supape evacuare - 1 buc; 4. Garnitura - 1 buc; 5. Ax came - 1 buc; 6. Vanos ax - 1 buc; 7. Kit distributie - 1 buc; 8. Filtru ulei - 1 buc; 9. Ulei Castrol EDGE 5W-30 5l - 1 buc; 10. Antigel G12+ 1l - 3 buc; 11. Chiulasa - 1 buc. Manopera inlocuit chiulasa.
