
Servicii de reparare Hyundai Tucson cu nr. de inmatriculare CT26API apartinand A.P.I.A.Constanta

I.D.: 44740678

Data publicarii	04.12.19	Coduri CPV	50110000-9
-----------------	----------	------------	------------

Pretul estimativ: 1.798,22 RON - 1.798,22 RON

Descriere: Servicii de reparatii constând in: -inlocuit acumulator 95AH -inlocuit alternator. Inlocuit: -antigel G12 1l 2 buc -apa distilata 1l 1 buc -alternator 1 buc -acumulator 95AH 1buc Total manopera 161,00 ron Total piese 1637,22 ron
