
Reparatie Stihl Mas Tuns Iarba MB6.2RH

I.D.: 71237817

Data publicarii 12.07.22

Coduri CPV

50800000-3

Pretul
estimativ: 394,29 RON - 394,29 RON

Descriere: Stihl Carburator 30003637-1 buc,293.445 lei Lucrari service si reparatii scule-8
buc,12.605 lei
