
Reparatie microbuz HD-08-UCM

I.D.: 62283352

Data publicarii	22.10.21	Coduri CPV	50110000-9 34300000-0
-----------------	----------	------------	-----------------------

Pretul estimativ:	2.267,23 RON - 2.267,23 RON
-------------------	-----------------------------

Descriere: Reparatie auto la microbuzul Mercedes Benz Vito cu nr. de inmatriculare HD-08-UCM (COLIER ESAPAMENT, CAMERA DETENTA, SENZOR PLACUTE FRANA, ETRIER FRANA, COLIER ESAPAMENT, SET PLACUTE FRANA, COLIER, SUPORT ETRIER)
