

Reparare pompa WILO

I.D.: 54843258

Data publicarii	04.03.21	Coduri CPV	50511100-1
-----------------	----------	------------	------------

Pretul estimativ: 3.879,82 RON - 3.879,82 RON

Descriere: Reparare pompa Wilo constand din: demontare ansamblu pompa, rebobinare stator, reconditionare cota etansare ax, inlocuire kit etansare mecanica superior si inferior, inlocuire rotor turbina, montare, ermetizare probe
