



Servicii reparatie UPS ABB DPA250

I.D.: 43597733

Data publicarii	22.07.19	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Pretul estimativ:	2.013,03 RON - 2.013,03 RON
-------------------	-----------------------------

Descriere:	Manopera diagnosticare si inlocuire placa controler UPS ABB DPA250
------------	--
