

## Diverse piese de schimb

I.D.: 99028673

---

Data publicarii	19.06.24	Coduri CPV	34913000-0
-----------------	----------	------------	------------

---

Pretul estimativ: 5.760,93 RON - 5.760,93 RON

---

Descriere: POMPA CENTRALA AMBREIAJ 2100322FTE X1 BIELETA ANTIRULIU 36090 01 X1 LICHID FRANA DOT4 1401-00-0003E 1L PFB401SE FBX100 95002200TX X1 12-01-02-0631 SOLENOID ELECTROMOTOR 231267 CAR X1 CUPLA RAPIDA AUTOMATA FI6 [MPUC06] CPUC6/4 22170F[A:019836] X4 CUPLA RAPIDA AUTOMATA FI8 [14-07-00-0610] CPUC8/6 22171F X4 CILINDRU RECEPTOR AMBREIAJ 4.67352 X1 13-02-01-0271 LAMPA SPATE MB. ACTROS TD02-50-001L [A:0016266] L0254LE/SE TL-ME001L X1 BEC 24V 21W BA 15S(SEMNALIZARE) 008511100000 0447[A:000387] X6 BEC 24V 5W BA 15S(CIREASA) 004627100000 032958 0515/Z[A:000390] 1987302510 8GA 002 071-241[A:009098] X6 SIGURANTE BUC PLATE 10A[12-05-00-0013] BP10A X10 SIGURANTE BUC PLATE 15A BP15A X10 TUB PLASTIC NEGRU FEBI 7726 FI12X1.5 [14-07-00-0014] T12/100M X1 CUPLA RAPIDA AUTOMATA FI12 [14-07-00-0090] CPUC12/9 06256F 22175F[A:0136433] 14-07-00-0470 X2 CUPLA RAPIDA COTITA FILETATA FI12/M16 [14-07-00-0488] MPL12-M16X1,5 CPL12/9-M16X1.5 X2 CUPLA RAPIDA FILETATA 22X12 FEBI 22222 FE[113472] CPC12/9-M22X1.5 ZLW-12/M22[A:034213] X2 CAMERA FRANARE TAMBUR 16/24[RL3530RA1] CAP TRACTOR 35304500050 14-05-00-0682 X1 SAIBA COMBI 3/8" BS023 X4 REDUCTIE M16/M22 [14-99-00-0091] [14-99-00-0065] 5CM-16-22 14-99-00-0015 X2 ROLA INTINZATOARE JCB 4CX 320-08628-AN X1 CUTIT 63-RM-17 X20 KIT DE ASAMBLARE CUTITE 63-RM-17 X1 CUREA 8PK2120 SCANIA DAYCO 8PK2113 FEBI 34143FE X1

---