

---

## Reparatie bidistilator model GFL 2014

I.D.: 101280397

---

Data publicarii	09.08.24	Coduri CPV	50421000-2
-----------------	----------	------------	------------

---

Pretul estimativ: 1.490,00 RON - 1.490,00 RON

---

Descriere: Reparatie bidistilator model GFL 2014 (nr. inventar 203563) 1. Constatate defectiuni - 300 Ron 2. Inlocuire termostatului - piesa - 300 Ron - manopera - 280 Ron 3. Inlocuirea furcunelor de legatura interna intre bazinele bidistilatorului. (3 bucati) - piese 3 x 110 Ron = 330 Ron - manopera - 280 Ron

---