

---

## Servicii de reparare masina de spalat Candy

I.D.: 93414630

---

Data publicarii	14.02.24	Coduri CPV	50532000-3
-----------------	----------	------------	------------

---

Pretul estimativ:	430,00 RON - 430,00 RON
-------------------	-------------------------

---

Descriere:	Reparatie masina de spalat rufe Candy, inlocuit garnitura hublou la DGASPC. SECTOR 1 / Casa "Sf. Stefan"
------------	--

---