
SERVICE POMPA DOZATOARE / INST DOZARE HIPOCLORIT

I.D.: 94701226

Data publicarii	15.03.24	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.798,88 RON - 1.798,88 RON

Descriere: Servicii de service pompe dozatoare hipoclorit de sodiu / instalatie dozare, ce includ: - constatare stare pompa de dozare; - inlocuire piese de schimb; - verificare in functionare.
Piese de schimb: - supapa aspiratie 3/8": 1 buc - supapa refularw cap pompa: 1 buc - supapa injectie 1/4" - 3/8": 1 buc
