

---

## Reparatie Opel Vivaro SB 04 POA

I.D.: 43351669

---

Data  
publicarii 24.06.19

Coduri CPV 50100000-6

---

Pretul  
estimativ: 2.683,37 RON - 2.683,37 RON

---

Descriere: inlocuire motor si accesorii +manopera reparatie accesorii piese:pompa ambreaj, ulei motor  
+ filter. completare ulei servo directive. antigel

---