

---

## REPARATIE DACIA DUSTER DSV

I.D.: 98679098

---

|                 |          |            |            |
|-----------------|----------|------------|------------|
| Data publicarii | 11.06.24 | Coduri CPV | 50112100-4 |
|-----------------|----------|------------|------------|

---

|                   |                             |
|-------------------|-----------------------------|
| Pretul estimativ: | 1.292,44 RON - 1.292,44 RON |
|-------------------|-----------------------------|

---

Descriere: DACIA DUSTER CS 02DSV Bujii incandescente 4 buc - 265,55 lei Captor presiune filtru de particule cu furtun OE - 623,53 lei Diagnoza KTS - 84,03 lei Manopera - 319,33 lei Total fara TVA 1292,44 lei Total cu TVA 1538 lei

---