
Servicii de reparare masina de spalat ind. Lavamac/LN220

I.D.: 102429951

Data publicarii	04.09.24	Coduri CPV	50532000-3
-----------------	----------	------------	------------

Pretul estimativ:	6.400,00 RON - 6.400,00 RON
-------------------	-----------------------------

Descriere: Reparatie masina de spalat rufe ind. Lavamac/LN220 , inlocuit inverter Mitsubishi FR-D720S-E8 ,programat inverter , la DGASPC SECTOR 1 /Centrul de zi Vrancei
