

---

## Reparatie masina de spalat Candy

I.D.: 87780346

---

Data publicarii	04.10.23	Coduri CPV	50000000-5
-----------------	----------	------------	------------

---

Pretul estimativ: 725,00 RON - 725,00 RON

---

Descriere: - Constatat defect complex: 70,00 Ron - Inlocuit subansamblu pompa: 150,00 Ron - Igienizare traseu evacuare: 45,00 Ron - Pompa 40 W: 85,00 Ron1

---