

---

## **Servicii de reparatie ecograf CX50 prin inlocuire piesa DISK DRIVE**

I.D.: 78453714

---

Data publicarii	07.02.23	Coduri CPV	50421000-2
-----------------	----------	------------	------------

---

Pretul estimativ:	3.010,26 RON - 3.010,26 RON
-------------------	-----------------------------

---

Descriere:	Servicii de reparatie ecograf CX50 prin inlocuire piesa DISK DRIVE
------------	--

---