

---

## Servicii de reparatie auto Mercedes Sprinter

I.D.: 55046530

---

Data publicarii	12.03.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 4.144,47 RON - 4.144,47 RON

---

Descriere: Servicii de reparatie auto, inlocuit KIT BIELETA+CAP DE BARA 21449, BURDUF BIELETA DIRECTIE MB SPRINTER, bASCULA INFERIOARA FATA DREAPTA JTC,BASCULA INFERIARA FATA STG JTC2221, KIT RULMENT ROATA FATA 713667040, GREASE SPRAY VASELINA MO090204, RADIATOR RACIRE MOTOR 62519A,ANTIGEL 1L RE6001997196,APA DISTILATA,MANOPERA MECANICA ,

---