
REPARATII AUTO SKODA SUPERB

I.D.: 83848411

Data publicarii	20.06.23	Coduri CPV	50530000-9
-----------------	----------	------------	------------

Pretul estimativ:	634,45 RON - 634,45 RON
-------------------	-------------------------

Descriere:	REPARATIA CONSTA IN INLOCUIREA ETRIERULUI SPATE DR, A BOLTURILOR DE ETRIER CAT SI MANOPERA.
------------	---
