

Reparati pompe

I.D.: 67018858

Data publicarii	07.03.22	Coduri CPV	50532100-4
-----------------	----------	------------	------------

Pretul estimativ: 8.315,00 RON - 8.315,00 RON

Descriere: Reparatia consta in rebobinare , inlocuire rulmenti , inlocuire etansari, Reparatia electrica si hidraulica., Reparatia consta in rebobinare, inlocuire rulmenti, presutupe, ulei., Reparatia consta in rebobinat, inlocuire rulmenti, inlocuire etansari tip presutupa , ulei etc, Reparatia consta in rebobinare .
