
Reparat si rebobinat electropompa 7.5 kw

I.D.: 45852052

Data
publicarii 23.04.20

Coduri CPV 50532100-4

Pretul
estimativ: 2.902,70 RON - 2.902,70 RON

Descriere: Reparat si rebobinat electropompa 7.5 kw : 1. Conductor bobinaj = 980.50 ron 2. Manopera bobinaj = 480.30 ron 3. Rulment inferior = 520.60 ron 4. Rulment superior = 230.80 ron 5. Semeringuri , 9 bic = 112.50 ron 6. Inel etansare Oring = 97.00 ron 7. Cablu alimentare MYYM 4x2.5 mm = 135.00 ron 8. Ulei vegetal = 25.50 ron 9. Manopera lucrari mwcanice = 320.50 ron
