

Reparatie imprimanta Hp P1102

I.D.: 50846145

Data publicarii	19.10.20	Coduri CPV	50323200-7
-----------------	----------	------------	------------

Pretul estimativ: 336,13 RON - 336,13 RON

Descriere: Reparatie imprimanta Hp P1102 constand in: - inlocuire rola calda; - inlocuire rola presoare; - inlocuire fixing film; - remanufacturare cartus toenr Hp 85A
