
Servicii de reparat pompa

I.D.: 82627914

Data publicarii	22.05.23	Coduri CPV	50532100-4
-----------------	----------	------------	------------

Pretul estimativ: 9.920,95 RON - 9.920,95 RON

Descriere: UAT Comuna Pantelimon doreste sa achizitioneze pachetul ce consta in servicii de inlocuit bobina contactor, conductor bobinaj, rulmenti.
