
Servicii de reparare a automobilelor

I.D.: 66581820

Data publicarii	22.02.22	Coduri CPV	50112100-4
-----------------	----------	------------	------------

Pretul estimativ: 368,40 RON - 368,40 RON

Descriere: MATERIALE: BOBINA INDUCTIE - 1 X 149.58 RON + TVA SOLUTIE SPALAT - 5 X 5.88 RON + TVA MANOPERA; SPALAT AUTOTURISM INTERIOR/EXTERIOR - 1 X 29.41 RON + TVA VERIFICAT PROBLEME MOTOR ,INLOCUIT BOBINA PORNIRE - 2 X 80 RON + TVA
