
Reparatie instalatie HVAC + pierderi aer

I.D.: 89861711

Data publicarii	23.11.23	Coduri CPV	50113100-1
-----------------	----------	------------	------------

Pretul estimativ:	5.243,06 RON - 5.243,06 RON
-------------------	-----------------------------

Descriere:	Verificat + remediat instalatie HVAC si verificat + remediat pierderi aer instalatie aer comprimat Mercedes-Benz Tourino A10656
------------	---
