

Reparatii tamplarie

I.D.: 50189595

Data publicarii	29.09.20	Coduri CPV	44221000-5
-----------------	----------	------------	------------

Pretul estimativ: 647,06 RON - 647,06 RON

Descriere: Inlocuit butuc yala usa aluminiu 2 buc, inlocuit butuc yala usa PVC 2 buc, inlocuit broasca monopunct 1 buc, inlocuit sild usa 1 buc, inlocuit contraplaca usa 1 buc
