
REPARATIE CENTRIFUGA II C60 LABORATOR

I.D.: 41338856

Data publicarii	21.01.20	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.373,95 RON - 1.373,95 RON

Descriere: Constatate defect * Depanare modul alimentare * Inlocuire PANOU COMANDA * Inlocuire CARCASA, * Inlocuire perii carbune la rotor * Curatare,gresare mecanisme TESTARE ELECTROSECURITATE PRELUARE,DEPANARE,RETUR,PROBE FUNCTIONALE Tine loc de comanda ferma
